



IMAGING TECHNOLOGY

RELEASE NOTES

IONODES PLUG-IN FOR MILESTONE

VERSION 1.0.2.6

January 10, 2024

FIRMWARE 1.0.2.6

RESOLVED ISSUES

- Fix an issue that caused problem when a device port was not correctly configured.

NEW FEATURES

- Added support for a third display.
- Added support for SSL streams

KNOWN ISSUES

FIRMWARE 1.0.2.3

RESOLVED ISSUES

- Improve performance when fetching Device list.
- Fix an issue that caused problem when a device port was not correctly configured.

NEW FEATURES

- Added support for Milestone SSL streaming.
- Added support for the R300 product.

KNOWN ISSUES

- If you physically unplug a live camera, the image on the SDS is going to freeze.

FIRMWARE 1.0.2.2

RESOLVED ISSUES

- Fix an issue where we would send IPV6 address to the SDS.
- Error messages when sending a view to a SDS have been collected in a single error message box.
- Fix an issue that generated an exception when trying to send a view containing a deleted camera.

NEW FEATURES

- It is no longer needed to manually enter the imaging server in the SDS configuration.
- Now supporting devices on multiple imaging servers.
- Now supporting the selection of the camera stream to send to the SDS.

KNOWN ISSUES

- If you physically unplug a live camera, the image on the SDS is going to freeze.

FIRMWARE 1.0.1.0

RESOLVED ISSUES

- No new resolved issue.

NEW FEATURES

- Added support for the Milestone Imaging Server as a data source. The plug-in supports connecting to a Milestone Onvif Bridge or to a Milestone Imaging Server as a valid data source.

KNOWN ISSUES

- If you physically unplug a live camera, the image on the SDS is going to freeze.

FIRMWARE 1.0.0.3

RESOLVED ISSUES

- Creating a blank SDS entry (all fields empty) no longer causes that SDS entry to be locked and unmodifiable.
- The plugin page now always displays feedback if there are more SDS entries detected than the maximum number allowed by the plugin license.

NEW FEATURES

- No new feature.

KNOWN ISSUES

- No known issue.

FIRMWARE 1.0.0.2

RESOLVED ISSUES

- Fixed a condition preventing the user from adding new Secure Display Stations while in trial.
- If the number of Secure Display Stations exceeds the number of license activations, the plugin now requests that the extra devices be removed.

NEW FEATURES

- No new feature.

KNOWN ISSUES

- No known issue.

FIRMWARE 1.0.0.1

RESOLVED ISSUES

- No new resolved issue.

NEW FEATURES

- Added Licensing (contact IONODES Sales for details)

KNOWN ISSUES

- No known issues.

FIRMWARE 1.0.0.0

RESOLVED ISSUES

- No new resolved issue.

NEW FEATURES

- New plug-in for Milestone XProtect that allows camera views from the Smart Client to be replicated on IONODES Secure Display Stations.

KNOWN ISSUES

- No known issues.

